


S.S. "CAYIAS"

With reference to the Hamburg Surveyors' letter of the 7th instant, it is submitted that they be requested to forward particulars of the scantlings of the upper deck bridge, which from the midship section appears to be a structural part of the vessel's topsides and from the profile plan to extend practically the whole length of the bridge; also it is not quite understood whether all the 8 watertight bulkheads reported extend to the upper deck or whether some of them extend to the second deck only.

*Dr. 7/6/23
and 11th.*



BB
11.6.23

2019
Lloyd's Register
Foundation

W602-0013