

10,30.

19 MAY 1931

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME Steel Twin Sc. "RUY BARBOSA" Rpt. Ham. No. 19881

he remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

re of Survey

The 2nd S.S. No.2, due 4.31, has been partly held.

The Hamburg Surveyors now report the vessel placed in dry dock, bottom cleaned and coated and the special survey advanced.

Additional girders under the weather deck and the two decks immediately below and pillars have been fitted in No.3 hold and the sheerstrake plates at the ends of the bridge renewed of increased thickness in accordance with approved plans and minor alterations effected.

It is submitted the vessel appears worthy to remain as classed with record of survey 4.31.

100A1
With freeboard
4.31 Ham.

W.L.
18.5.31.

To complete the survey:- See report.



© 2019

Lloyd's Register
Foundation

W602-0039