

# Lloyd's Register of Shipping,

3, Steinhoeft,

Hamburg, 15th April, 1931.



LLOYD'S REGISTER  
RECEIVED  
17 APR 1931  
And. 20/4 22/17/4  
LONDON

Dear Sir,

The s.s. "RUY BARBOSA" No 83017 in the Society's Register Book, is now at this Port and the Owners propose to effect repairs to the sheer strake and bulwark plating at the fore and after ends of the bridge at which parts repairs were effected to the vessel when she was under survey at this Port at previous occasions (Refer Hamburg Reports Nos. 18749).

In view of the cracks which have developed in the sheer strake plating it is now proposed to renew these plates at the ends of the bridge of increased thickness and fit doublings and some additional strengthening. With a view to further strengthening the structural arrangements in No 3 hold the Owners propose to fit additional deck girders at the weather deck and the two decks immediately below, these girders to extend the full length of the hold and new pillars are to be fitted at positions as indicated on the accompanying plans.

Duplicate copies of three sketches showing the proposed arrangements are being forwarded herewith and I shall be glad if these plans could be examined at the earliest possible moment and this Office advised by cablegram that the arrangements as now proposed can be accepted. The Owners have requested a

© 2019  
Lloyd's Register  
Foundation  
W602 0048 02

number of repairers at this Port to tender for the work and as the work is to be commenced immediately the contract is assigned the Owners' Representatives have asked for the earliest possible consideration of the proposals now submitted.

I am, Dear Sir,

Yours faithfully

J. Chisholm

The Secretary,

LONDON



© 2019 Lloyd's Register Foundation

RECEIVED BY THE SECRETARY  
13th FEB 1931

Delivered to the Office of the Secretary

W602-0048 2 1/2

