

D REPORT on the

Blumer & Co. 757.

See letter sent to Bineham 17/7/13
Regarding amended scantlings if
deeper loading is required with
lengthened bridge.

W.D.

18.7.13



© 2021

Lloyd's Register
Foundation