

COPY.

See S.F. Reg. No 5853

Lloyd's Register of Shipping.



Port SAN FRANCISCO

AUGUST 4th, 1929

This is to Certify that I have

XXXXXXXXXX
Surveyed the Boiler and Machinery of the Steel Twin Screw Steamer
"TAHITI", of London, 7898 tons gross register, while lying in dry
dock at this Port on account of loosing starboard propeller while
making a landing at Pier #33 San Francisco, California, 6:55½ A.M.
AUGUST 2nd, 1929 - - - - -


and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have
recommended that the record of L.M.C. be continued -
- - - - -

XXXXXX
made in the Register Book in the case of this vessel, subject
the damaged propeller blade being faired at next docking, also
the E.W. repairs to forward end of port forward single ended
propeller being again examined by February 1930.

(sgd) S J READER

Engineer Surbeyor to Lloyd's Register.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—
while the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is
understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for
accuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other
publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents
of the Society."



Lloyd's Register
Foundation
W605-0226