

COPY.

Lloyd's Register of Shipping.



Port Sydney, N.S.W.

12th July 1929.

This is to Certify that I have

Starboard & After Port

Starboard Propeller Shaft & Repairs to Port Propeller

Surveyed the Boilers and Machinery of the

T. S. S. "TAHITI"

of London.

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have

Recommended that the record of Starboard Propeller Shaft

seen 7.29

be made in the Register Book in the case of this vessel, and will be eligible for fresh record of Boiler Survey with date to be noted in the Register Book when the Survey is completed.

(SGD) Jas. C. ERSKINE.

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."