

Limitation List

The T.S.(C.L.) was drawn and upon examination, the liner was found to be slack (on one side only) at the extreme after end and a shallow ring of corrosion was evident.

This is not considered serious in the meantime and it is recommended that the shaft be examined again before the end of June 1932.

By
/s/

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

B.S. due 8. 31. Now held

It is submitted that this vessel is eligible for THE RECORD.

B.S. 6. 31

It is submitted that this vessel is eligible to remain as CLASSIFIED

Subject to T.S. being read before end of 6. 32

Y. K. 26. 6. 31



© 2021

Lloyd's Register Foundation