

from the faying surfaces? *Yes* Do any rivets break into or through the seams or butts of plating? *very few*  
 Are the butts of Plating, Stringers, &c., properly shifted and strapped? *Yes*

*Compulsory*

*Copy*

Rpt. 12.

FREEBOARD VERIFICATION FORM FOR STEAMERS.

Port *Belfast* (When received in London Office)  
 Vessel's Name *Demosthenes*  
 Official No. \_\_\_\_\_ No. in Reg. Book *1*  
 Port of Registry (~~For Foreign Vessels~~) \_\_\_\_\_  
 Iron or Steel *Steel* State whether Classed by Lloyd's Register *Yes*  
 Name of Owners *G. Thompson & Co.* Date of Verification *21<sup>st</sup> June 1911*

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

|                                                                                                                                                                                         |                                               |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------|
| From centre of disc to top of statutory deck line                                                                                                                                       | <del>5</del> ft. <del>4</del> ins.            |
| From centre of disc to top of statutory deck line }<br>at awning or part-awning deck . . . }                                                                                            | 13 ft. 8½ ins.                                |
| Fresh water line above centre of disc . . . . .                                                                                                                                         | 7½ ins.                                       |
| Indian Summer line above centre of disc . . . . .                                                                                                                                       | 6½ ins.                                       |
| Winter line below centre of disc . . . . .                                                                                                                                              | 6½ ins.                                       |
| <del>Winter North Atlantic line below centre of disc</del>                                                                                                                              | <del>1</del> ins.                             |
| Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of <i>2" titoul on wood or iron deck with the vessel's side</i> | at main, spar or upper dk. <del>1</del> ins.  |
|                                                                                                                                                                                         | at awning or pt. awning dk. <del>1</del> ins. |

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

(Signed) *S.O. Kendall* Surveyor.

(To be filled up in London Office.)  
 Statement No. *21704* Date of Committee's Minute *20.6.11*  
 Moulded Depth for record . . . . . *42* ~~ft.~~ *8* ~~ft.~~ ins.  
 Freeboards compared and found correct by \_\_\_\_\_ date *21.7.11*  
 Is fee paid? *new vessel* Form for Certificate *A*  
 Instructions \_\_\_\_\_ date \_\_\_\_\_  
 Certificate written \_\_\_\_\_ Noted for posting \_\_\_\_\_

*Classification 100M Awning Deck  
 Conditional on the above freeboards.*

2m.8.10.—T.

I am of opinion this Vessel should be Classed *"100 Awning Deck"*  
 With, or without Freeboard, as condition of Class *With freeboard*

*S.O. Kendall*  
 Surveyor to Lloyd's Register of British and Foreign



© 2021  
 Lloyd's Register  
 Foundation