

Twin S. S. "Benalla"

Guernsey Report 16402.

As the Surveyor reports that the vessel dragged her anchor at the Tail of the Bank & a diver states that one of the propellers has sustained some damage, & that it has been arranged to place the vessel in dry dock at London for examination."

It is submitted that the Macc^h is eligible to have the record of + LMC. 2-13. Subject to the propellers & the bottom being exam^d when in dry dock at London.

LH Meek
10/3/13.

1100-019M