

by Chief Ship Surveyor 25. 3. 13

Received from Chief Ship Surveyor

EL'S NAME M 1/5/5 "Bnalla"

Rpt. Low

No. 75474

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey DAMAGE.

Damage through to propellers

now repaired as follows:-

|                                     | Plates  | Frames | R. Frames | Floors | Beams | Str. Plates | Dk. Plates |
|-------------------------------------|---|--------|-----------|--------|-------|-------------|------------|
| Renewed .....                       | (Large handwritten scribble covering the table) |        |           |        |       |             |            |
| Removed and faired or repaired..... |   |        |           |        |       |             |            |
| Faired or repaired in place.....    |   |        |           |        |       |             |            |

Other items:-

Vessel rammed in Dry Dock, the bottom cleaned & coated.

It is submitted the vessel is worthy to remain as classed with record of Survey 3.13 Low as recommended

100 A.1  
3-13 Low

AP. 25. 3. 13