


Old Report n^o 23460

It is submitted that it should be pointed out to the Old Surveyors that in ^{they forwarded from the Engine Builder} their letter, of May the 27th, enclosing one from the Engine ~~Builder~~, submitting the proposed alteration in the pumping arrangements. The H. S. was given as 1243 ft. making the N.H.P. 71.6. Whereas from the above Report it now appears the H. S. is 1423 ft making the N.H.P. 78. In similar cases in future they should be more careful that correct details are given.

Dr Sd 1/11/07



© 2021
JLC 30.10.07

Lloyd's Register
Foundation

W811-0067