

3.3. "Birchleaf"

review of the survey recently held on the
"Parrelleaf" & 33 "Birchleaf", in which somewhat
similar shaft trouble to that which has
occurred in the "Birchleaf", has been
traced to low viscosity lubricating oil,
and submitted the following cablegram
to the New York Office.

"Birchleaf" inform Salmon Shaft trouble
no similar vessels traced to low
viscosity lubricating oil."

ARR

18.4.17

18.4.17.

JM



© 2020

Lloyd's Register
Foundation

W613-0030