

Ship Surveyor 2. 1. 17

Received from Chief Ship Surveyor

1E single Stl. S.S. "BIRCHLEAF".

Rpt.

Sld.


No. 26886

of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also pointing out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points entered in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

It is submitted before this case receives consideration the Surveyors should be requested to forward the approved plan of the transverses in the fore peak.

They should be informed that it is concluded transverse beams are fitted in the oil tank as shown on the approved midship section, and that the tank top longitudinals are 7 x 3 x .43 at the ends, as also shown.



2. 1. 17



© 2020

Lloyd's Register
Foundation

W613-0039