

F.E.

Chief Ship Surveyor 18.8.19

Received from Chief Ship Surveyor

NAME

Steel S. S.

"T. 19"

Rpt.

Jul

No. 30102

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

36.37

Depth "d"

11.66

Drawing: Table No. 3 page 9

Description

Single Angles as approved

Longitudinal No.

4909

Proportions

$$\frac{\text{Length}}{\text{Depth}} = 10.38$$


Deck Sheerstrake .50 of an inch instead of .36 as required

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed ∇ 100 A-1. (Steel) "Steam Trawler" as recommended.

 ∇ 100 A-1. (Steel) "Steam Trawler"

1 DK

B.K. 8", 4 B.H., Cem., Lloyds Arch., Q 74', F 31',



20.8.19
© 2020
Lloyd's Register
Foundation

W613-0085