

W615-0237

m.7.30.

Report to Chief Surveyors _____ Received from Chief Surveyors _____
 VESSEL'S NAME Stl S CALDER Report lv No. 97993

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey P. Entry When due _____ Revised Rules _____

✠ 100 A. I. (Steel)

1 D^k (Stl)

Cell D.B a.u E 73', f 90' 193t, F.P.T. 17t, A.P.T. Hot.

F.K., 5 B.H., Cem, Lloyd's A & CP.

P 38', B 85', F 35'.

July 17.12³⁰

© 2020

16.12³⁰

The Surveyors should be requested to state whether the thickness of the Keel plate and E strakes have been increased as per ^{see} memo list of extra scantlings on midship section, or as reported.

Lloyd's Register Foundation