

1

Fulmar

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel S.S. "WAR YARD". Report Liv. No. 79060**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 245092.)

Nature of Survey _____ When due _____

The dwtton pump has been dispensed with as approved in Standard Vessels.

The chain cables have been supplied in accordance with the Modified Rule, Circular 1304, and 30 fathoms require to be supplied to bring the length of chain cable up to the requirements of Table 31

100 A.L. (Steel) Shelter Dk. with freeboard.

1 Dk. (Steel) and Shelter Dk. (Steel).

Cell DB 224' 408. FPT 63t. APT 18t.

FK. Collision Bulkhead to Shelter Dk. 3 BH to Upper Dk.

Cem. Lloyd's A. & C.P.

The Certificate of Classification to be endorsed in ^{in Shelter two Dks.} "Cargo buttens not fitted," and the same notation to be printed in the Register Book.



© 2020

25. 5. 19

Lloyd's Register
Foundation