

by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

4 FEB 1928

SHIP'S NAME Stl.S.S. "PADDINGTON".

Rpt. Nwc.

No. 82287.

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

of Survey \_\_\_\_\_

The Newcastle Surveyors report this vessel placed in dry dock, the requirements of the S.S.No.1, due 5.28, partly complied with and the bottom cleaned and coated.

Damage through grounding has been repaired as follows:-  
3 shell plates renewed, 27 shell plates, 40 frames and 12 floors repaired and minor repairs effected.

It is stated the survey will be advanced from time to time as opportunity offers.

It is submitted the vessel appears worthy to remain as classed, with record of survey 1.28. *as recommended.*

100A1.  
1.28. Bty.

© 2020  
Lloyd's Register  
Foundation

3. 2. 28.

W621+0016