

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

*2/6/09*  
*St. St. Cardiff City*

Report

*As*

No.

*27779*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

*First entry*

When due

+ 100A1 (stud)

1 Dr. (et)

*Stud Due*

NB. F.P.T. 326

BK 6" S.B.H. Conn. Lays A+B QSI B11 F22 Nchly Aff

*R.R.H.*

*C.H. 2/6/09*

*It is concluded the Surveyors are in error in stating that the turnline is of 2" hemp & that it is of stud wire & if so they should state the breaking test.*



© 2020

Lloyd's Register  
Foundation

W621-0055