

24 NOV 1928

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME *Stl Se. AUSTRALIC* Rpt. *Lat* No. *7319*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey *DAMAGE. & Alterations*Damage through *cause not stated*

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....	1						
Faired or repaired in place.....	2	2					

Other items:- *Vessel placed in drydock, bottom coated.*

Alterations. Have been made in way of H^o 3 hold to enable palm oil to be carried, additional bulkheads etc being fitted in accordance with the approved plan & girders fitted under the shelter deck as required.

It is submitted the vessel is worthy to remain as classed with record of Survey 10.28 as recommended. *mutation "Carrying vegetable oil in H^o 3 hold."*


100 A.1.

Shelter deck with fbd.

10.28 Lat

*Carrying Vegetable Oil in H^o 3 hold.**Amend GBH 67 BH in R.B.*

W621-0126



© 2020
Lloyd's Register
Foundation