

1

Wreck 53.B

W624-0057

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME *Steel S.S. "Bayeskimo"*Report *Gls.*No. *42031***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey _____

When due _____


+100 AI (Stl) Shelter Deck with freeboard.

1 DK (Stl) & Shelter DK (Stl)

Cell. DB. a 58' u E 23' f 77' 239t APT 26t

FK, Coll. BH. 6 Shelter DK, 4 BH 6 upper DK, Cem, Lloyds A+CP. B. 66' F 26' on Shelter DK.

It is concluded the bottom plating of Bulkhead 64 is as approved but the Surveyor should be requested to state if this is so.



2020

Lloyd's Register
Foundation

7.7.22