

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C. 3.

27th October, 1925.

Dear Sir,

With reference to the classification in the Society's Register Book of your Wood Schooner "COMBACK", which was reported to have been refloated on 1st February after having stranded on 20th January off Sandy Hook, I beg to acquaint you that a communication has been received from the Society's New York Office from which it appears that the Surveyor at Jacksonville has been informed by your goodself that the vessel is a "total loss due to stranding".

The Committee have had the case before them and I am directed to inform you that in the circumstances it has been decided to insert a record of "Stranded 1.25 - Refloated" against the vessel's name in the Register Book, and to expunge her class at the same time in accordance with the usual practice.

I am, Dear Sir,


Yours faithfully,

Assistant to the Secretary.

M.L. Fleishel, Esq.,

P.O. Box 136,

JACKSONVILLE, Fla., U.S.A.



© 2020

Lloyd's Register
Foundation
W624-0102