



Repairs W & T

H.P. & M.P. piston Rods skimmed up

H.P. top end brasses renewed

Thrust white metal shoes - renewed

Feed pump Ram skimmed up, new neck & gland bush

Bilge " " " " " " " " " " " "

air pump Rod skimmed up " " " " " " " "

Condenser aft water space - renewed

main steam pipe annealed & tested & found satisfactory

Condenser tested & found tight

Dynamo:-

Cylinder bored out, new piston & rings fitted

Bailer Repairs

2 combustion chamber stays - renewed

Port Lower manhole door built up with E.W. T  
door refitted

Minor Repairs to bailer mounting

W.S.W.

S.S. No. 1. due 9.30 Suwey

now held on machinery  
Minor repairs effected

It is submitted that  
this vessel is eligible for  
THE RECORD

date 9.31

How

17.9.31

N.B.—If this Report is copied by copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register  
Foundation