


S. S. Perlak

bal 5118.

The surveyor should be requested to state whether the old donkey boiler has been removed from the vessel whether the donkey boiler stop valve is arranged so that steam from the main boiler cannot enter the donkey boiler

clerk ^{lv} 18/2/21

^{lv}
10/2/21



© 2021

Lloyd's Register
W625-0079
Foundation