

24 OCT 1930

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME Steel Sc.Sr. "CASSIS"

Rpt. Nwc. No. 86336

arks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/32).

urvey

The class is subject to the upper portion of the middle line bulkheads being specially examined at the next special survey.


The 2nd S.S. No.1 became due 8.30.

The Newcastle Surveyors now report that the vessel has been placed in dry dock and a general examination made with a view to drawing up a specification of repairs required.

General wastage was observed of the transverse bulkheads, centre line bulkheads and bulkhead stiffeners and brackets, side longitudinals, fore and after bottom girders, transverses, trunk sides, main and weather deck plating.

The vessel is laid up and nothing further has been done.

It is submitted action be deferred.



W.R.M.A.
22.10.30.



© 2020

Lloyd's Register
Foundation

W 627 - 0081

8.30 being carried out within the year of grace