

3m, 11.39.

13 FEB 1943

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "CLEANDER"

Rpt. Bom.

No 6091

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

The Bombay Surveyor reports the tanker placed in dry dock, bottom coated and on account of damage due to grounding, 3 shell plates renewed and repairs effected to shell plating, framing, bulkheads, brackets etc.

It is submitted the vessel appears worthy to remain as classed with record of survey, 11.39.

100 A1

11.39 Bom.

Carrying Petroleum in bulk.

Fitted for oil fuel etc.

all
8.2.40



© 2020

Lloyd's Register
Foundation