

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, ladders, and of the inner bottom plating, especially in the boiler space.

A Special Survey, Date of last Survey and of Periodical Surveys.

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

18th September, 1931.

Dear Sirs,

S.

With reference to the classification in the Society's Register Book of the steamer "DUMFRIES", I beg to acquaint you that the Committee have had before them to-day a report received from the Society's Surveyors at Barrow from which it appears that the vessel has been examined afloat after grounding.

Soundings were taken and no leakage was found, but it is recommended that the vessel be examined in dry dock at the first convenient opportunity.


The Surveyors further report that the Boiler Survey, which became due in May last and was partly held in June and July, has been completed, and the Committee have assigned to the vessel a notation of 'B.S.6,31'.

I am, Dear Sirs,

Yours faithfully,

pro Secretary.

Messrs. Griffiths, Payne & Co., Ltd.,
3, Pier Head Chambers,
Bute Street,
CARDIFF.



Lloyd's Register Foundation
W670-6094

2
Edward

...register is open without fresh record of survey subject to the vessel