

offered his services for this purpose and to whom and why they were declined Yes Society's Freeboard (if assigned) as {
painted on Ship and now verified }

Was a damage report made by whom? ho.

15 SEP 1931

5m.7.30.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Steel Sc.Sr. "DUMFRIES" Rpt. Brw. No. 2415

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

Nature of Survey _____

This vessel is reported by the Barrow Surveyors to have been examined afloat after grounding, soundings taken and no leakage found.

The Surveyors recommend the vessel be examined in dry dock at the first convenient opportunity.

It is submitted action be deferred and the Owners informed of the Surveyors' recommendation.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.



© 2021 Lloyd's Register Foundation
159/31

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book to remain as now classed in the Register Book without fresh record of Survey, "to remain as classed and