

1

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

22 NOV 1932

SEL'S NAME

Sh Se "CANADIAN RANGER"

Rpt.

ML

No. 3652

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

DAMAGE.

ure of Survey

Damage through

striking a dolphin + propeller fouling a rope.

now repaired as follows:-

	Plates	Frames	R.Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....	2						
Other items:-	Vessel placed in dry dock.						

Bottom coated.

It is submitted the vessel is worthy to remain as classed with
 record of Survey 10.32 as recommended.

100A1
 10.32 ML

MLB
 19.11.32



© 2021
 G.S.

Lloyd's Register
 Foundation

W630-0132