

Engine Room .. }  
TON

Proportions—Depths to Length—Upper Deck Room at

TELEPHONE MAIN 7017

Cablegrams :  
"PORT WARDEN, MONTREAL"

# Lloyd's Register of Shipping

42 ST. SACRAMENT ST.

LLOYD'S REGISTER,  
LONDON.  
RECD 8 4 1919  
ANSD

MONTREAL July 24th. 19 19.

The Secretary,  
London, England.

Dear Sir:-

S.  
I beg to acknowledge receipt of  
your letter of July 8th.

"CANADIAN RANGER" report 1692. I have to state that the  
rivetting of the bridge side plating is as approved. A  
hand pump was fitted to the fore peak tank top, tested,  
and found to be working satisfactorily. The second  
deck beams were as approved.

Yours very truly,

*W. J. Alderson*



© 2021

Lloyd's Register  
Foundation  
W630-038

W630

Referred to the Chief Ship Surveyor.

*CR*

1888 - 8

Also for Mr. S. A. Hill to note.

*M*  
*8.8.19*



© 2021

Lloyd's Register  
Foundation

Loss above Crown of  
Engine Room ...

119.

ESSEL'

ceived by

The r

Tra

Fra

Lo

R

b

a