

(Donkey)

of Main Boilers 4 Owners Federal Steam Navigation Co. Owners' Address

4E

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

REL'S NAME

Pareora

Rpt.

Tal  
Py

No. 8184

22431

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

re of Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

Not due 1.33.

Sh due 9.33.

Engines & Boilers examined  
in accordance with Circular 1608  
with a view to the vessel proceeding  
to Japan for demolition.

Propeller & Fastenings examined  
in dry dock after grounding.

Submitted action be  
deferred.

DN 11/1/34



© 2021

Lloyd's Register  
Foundation

W670-0188

as per is eligible in my opinion to remain as now class

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.