

12 FEB 1921

ved by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME Steel S.S. "TREDENHAM" Rpt. Cff. No42495

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/22.)

ure of Survey

This vessel was built in 1915 and classed with Germanischer Lloyd.

The Cardiff Surveyors report the vessel has been placed in dry dock and examined throughout.

The bottom has been cleaned and coated and repairs due to damage and wear and tear effected.

The Committee's requirements for classification have been carried out except that web frames 36" x 10/20" require to be fitted in the holds as compensation for the framing being slightly deficient in strength, and for the omission of two bulkheads, and the connections at the margin plate require to be examined.

In the Surveyors' opinion the vessel is in a fit condition to run for a further period of six months.

It is submitted notation of Cff.1.21 be assigned, (see footnote 3).

11. 2. 21.



© 2021

Lloyd's Register Foundation

W630-0205