

of CARDIFF.

20th January 1921.

James Barclay,

Mr. Lowdon, the representative of the Owners of the ex-German steamer

"FALKENFELS", now "TRIDITHAM".

3322 tons gross, 750 nominal horse power, of St. Ives, make a survey of the main and auxiliary engines and boilers, with a view to their being classed in this Society's Register Book.

The vessel was placed in the Mount Stuart Dry Dock Co., Dry Dock, Cardiff, on the 2nd December 1920, and on this and subsequent days while in dry dock and afterwards afloat in the Queen Alexandra Dock, Cardiff, the whole of the main and auxiliary engines and boilers were opened up for examination and these found or now put in good condition as follows

Propeller, two new blades fitted.

Stern tube stuffing box repacked, and brass nuts fitted to gland studs.

Bilge suction pipes repaired.

Condenser tested, Iron bolts in through stays wasted, now renewed in brass.

Weirs pump overhauled, valve spindle pins, piston rings, and rings for water buckets renewed, suction and delivery valves and seats, faced and refitted.



©2021

Lloyd's Register
Foundation

W630-0230 1/2

TUES. 25 AUG 1925

signed

No. of Main Boilers 4
No. of Donkey Boilers 1
Main Pressure 11
Boilers, when made (Sulphur) 1915
Owners Hain & S. Ltd (E. Hain & Sons) Port St. James London. V.
T.S.O. - Afloat in Dry Dock Mount Stuart

Particulars of C
rely as i
CHARACTER
or Special Sur
Last Survey
Official Survey

-2-

General service pumps taken to works and overhauled, cylinders
red out, piston rings renewed, water end rods trued up, new fibre
lives fitted, valve gear made good, pumps refitted in place.

Ballast pump, which also pumps from bilges, fitted with a
parate bilge suction. It is also fitted with a master valve,
ich separates tanks from bilges.

Dynamo engine overhauled, slide valve spindle trued up, neck
sh renewed, electric installation overhauled.

Ash hoist engine and fan engines overhauled.

Evaporator cleaned and overhauled.

Main Boilers. Leaking circumferential seam in forward boiler
alked.

All furnaces gauged and gaugings compared with those made
e months ago, and found in order, there is no appearance of
movement.

All mountings overhauled and ground in.

Furnace and smoke box doors, fittings, and air valves overhauled.

Pipes in way of hull repairs refitted.

Main and auxiliary engines, and boilers tried under steam and
nd satisfactory.

As far as can be judged from the inspection of the various
ts of the machinery and boilers now examined, I am of the opinion
the machinery and boilers of this vessel appear to be in a fit
ition to run for a period of six months.

James Barclay
SURVOR TO LLOYD'S REGISTER.



© 2021

Lloyd's Register
Foundation