

1m.12.20.

2

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Stk. Sc. "TOKUFUKU MARU"* Report *N. Yk.* No. *22970*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.32.)

No. *1* **SURVEY PARTLY HELD.**

When due

2, 23

When proposed to be completed

✓

Portion of Survey held, &c..

To Complete Survey all rule requirements to be carried out except dry docking.

Damage to plating through heavy weather to be permanently repaired at Owners convenience.

Stemframe rudder repaired by E.W. in July 1922 to be specially examined at next dry docking.

Rudder above the light waterline to be examined at each opportunity.



© 2020

25.7.23

Lloyd's Register
Foundation