

Gls 36714

Submitted the Owners be asked to state
then & where this donkey boiler is to
be fitted on board.

C. Hill
circ.

JH
1. 3. 17.

1. 3. 17.

© 2020



Lloyd's Register
Foundation