

S.S. "M E M P H I S".  
=====

It is submitted the Southampton Surveyors should be informed that it is regretted that they did not at once advise this Office when they held the condition survey on this vessel, that the boilers were not opened up for survey so that the matter could have been taken up with the Owners.

It is noted that an external examination was made of the boilers, and it is concluded that an external examination was also made of the engines. If this is correct, and so far as could be seen the vessel's machinery appeared in fit condition, a condition survey report on the machinery should be made out.

It should be clearly stated that no parts of the engines/<sup>or boilers</sup>were opened out for survey, and a limit of time given for holding a boiler survey.

ARRA

27. 1. 21.

U.S.S. R F



© 2020

Lloyd's Register  
Foundation

w636-0198