

COPY

Lloyd's Register of Shipping.

Port Kobe.

3rd. September 1931.



DAMAGE "A"

This is to Certify that

Y. J9.

the undersigned Surveyor to this Society did at the request of the owners' representative, survey the S.S. "YONAN MARU", 7154 tons gross, of Kobe, on the 24th. August 1931 and subsequently whilst the vessel lay in Osaka Iron Works, dry dock at Imo-shima, for the purpose of ascertaining the nature and extent of damage stated to have been caused by striking quay wall on the 1st. July 1931 at Portland, Oregon when leaving the port for Muroran.

For further particulars see Log Books.

The undersigned upon examination.

FOUND

Shell plating, Port Side.

No. 6 & 7 plates from forward end in strake 4th. below sheer strake indented.

No. 7 plate from forward end in strake 5th. below sheer strake slightly indented.

2 longitudinals bent.

RECOMMENDED

To be removed, faired and refitted.

To be faired in place.

To be removed, faired and refitted.

It was further recommended that all removals necessary to effect repairs be placed in good order.

Repaired parts to be recoated as before and shell plating (continued).

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."

(2)

Continuation of Damage Report "A" on the S.S. "YOHAN MARU".
Kobe, 3rd. September 1931.

to be hose tested on completion of repairs.

The above repairs have now been completed satisfactorily
as recommended.

Fee.....Yen 30:00
Expenses.....Yen 5:00

J. Jo.

ASSIST. SURVEYOR TO LLOYD'S REGISTER.



© 2021

Lloyd's Register
Foundation

W638-0039 1/2

This Certificate
"While the
either the Comm
ened by the Bo
negligence of

0-06-11 M