

Received by Chief Ship Surveyor 16.7.03

Received from Chief Ship Surveyor

VESSEL'S NAME *St. Lucia S.S. "Evelyn Grace"* Report *Hpl.* No. *12128*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

*First entry*

It is submitted that before this case receives the consideration of the Committee the Newcastle Surveyors should be informed that this vessel is reported by the *Hartlepool* Surveyors to have sustained damage through collision, and the vessel has proceeded to the Tyne where permanent repairs are to be effected at The Wallsend Slipway. The Newcastle Surveyors should therefore be requested to give the case the necessary attention, and on completion of the repairs to report upon the same on Form No. 8 for the information of the Committee with a view to the classification of the vessel.

*Ln to Nwc 16.7.03*

*C.H.J.*  
*16/7/03*



Hold	Quarter 'tween Dks.,	3 1/2	60	3 1/4	60	Deck. Material and thickness	Shon	9 1/2
	in Hold 2 Rows	5	60	5	60	Forecastle Deck Stringer Plate, b'dth & th'kns	60	12