

S. S. Macedonia.

It is submitted the writers be
informed that if no web frames had
been fitted in the hold spaces of
this vessel the Rules would have
required the depth of the built
angle framing to have been $8\frac{1}{2}$ "

13-6-12

sd 14.6

C. F.

14-6-12



© 2020

Lloyd's Register
Foundation

W639-0177