

4E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

Rosovic

Rpt.

Wellington No. 1348

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

Crank shaft coupling bolts becoming loose,

Several being found broken


Defective bolts renewed and crank shaft re-aligned

It is submitted that
this vessel is eligible to
remain as CLASSED.

A.S. No. 2 due 4.31
on 4.31

Y.R.

4.8.31



© 2020

Lloyd's Register
Foundation

W639-0208