

H 9-1-24
E 23-1-24

... painted on Ship and now verified

4

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Steel S.S. "ROSERIO"

Rpt.

Rot

No. 13369

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor

COMPLETION OF

S.S. No. 3

subject:- to some underdred shell plate being dealt with at owner's convenience

The

S.S. No. 3

partly held at

Cardiff, Calcutta,

now completed, and the following repairs done (due to wear & tear):-

4 shell plate removed & refitted, & 6 faired in place; 12 floors renewed & 5 faired in place, 10 Inter-Catals renewed, Tank Top last renewed in E.B. space, deck renewed under Donkey boxes. & minor repairs effected.

vessel cleaned in Drydock, bottom cleaned & recoated.

oil burning
Installation

It is submitted the vessel is worthy to remain as classed, with record of Survey 2.24 Rot and notation of S.S. C/P 103-4-23 as recommended.

without special condition.

100A.1.

Shelter Deck with Fbd.

without etc

2.24 Rot

S.S. C/P 103-4-23

Compartments

F.P. above 150° in DB.

[Signature]

8/3/24



© 2020

Lloyd's Register Foundation

W639-0233

Character Assigned

100A1 Without spl Cond
Shelter Deck with

[Signature]