

W639-0245

5m.7.30.

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

6 MAR 1931

VESSEL'S NAME Steel S.S. "PHYSA". Rpt. Sng. No. 4835.**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

Nature of Survey \_\_\_\_\_

The Singapore Surveyor now reports the vessel placed in dry dock, bottom coated, repairs effected to deck plating, casings forward cofferdam, hatch beams and fore and afters and minor repairs carried out.

It is submitted the vessel appears worthy to remain as classed with record of survey 2.31.

100 A. 1.  
Spar deck  
2.31 Sng.

The Certificate of Classification to be endorsed "Cargo buttons not fitted" and the same notation to be



© 2020

Lloyd's Register  
Foundation

clean  
da  
at  
me  
as  
pl  
al  
of W  
n Eng  
Mon  
ascerta  
redges  
ET  
f nois  
270  
oord)  
rth  
rps  
tanning  
ster B  
sed an

w clear