

No. of Feed pumps 2 ✓ Diameter of ditto 4" Stroke } 25" Can one be overhauled while the other is at work yes.

Rot. No 6745

It is submitted that a copy of this Report be forwarded
to the Amsterdam Surveyor for completion of survey.

A.R.R. J.B.M. 28/7/10

Re: - 28/7/10



© 2021

Lloyd's Register
Foundation

W645-0048

Length of plain part top Thickness of plates bottom } 5/8" Description of longitudinal jo

Material steel Thickness: Sides "1/16" Back "1/16" Top "1/16"