

W649-0037

F.E.

80,8,12

Received by Chief Ship Surveyor

7/2/3

Received from Chief Ship Surveyor

VESSEL'S NAME

At St Cyrena

Rpt.

Mr

No.

14582

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

61.16

Depth "d"

19.16

Framing: Table No.

3 page 11

Description

Bulb angle

Longitudinal No.

17614

Proportions

Length

Depth

= 12.89

Upper Deck Sheerstrake 04 less than required but compensated by increased width to give equivalent strength.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + 100 A-1. (2nd) as recommended.

Subject to the vessel being engaged exclusively in carrying cargo while trading.

+ 100 A-1 (2nd) subject to

1st (2nd)

W/B. See D/B 184 456t FPT 224t APT 36t
Fk. Immediate Bulkhead in fore hold disposed with 4 BH only. Gen. alloys as 60, 70, 814 F 85
"Mch 4 A/F"

W/B.

E.B.



© 2000

Lloyd's Register Foundation