

s/s "Fukki Maru"

Yka 3310.

o Koki.

It is submitted the Yokohama Surveyors should be requested to state the pressure to which the main steam pipes were tested.

It is concluded a spare set of coupling bolts has been placed on board & that a separate suction has been fitted in the engine room, but they should state if this is so.

See Yka 3310
9/8/mt

30/5/mt

W649-0120

DESCRIPTION OF INSULATION, PROTECTION, ETC.

The main and lower cell