

12/1 25 Port of Hull
Survey held at Hull Date, First Survey 18-12-24 Last Survey 3/11 1925
on the Wood, Iron or Steel SCK FIELD MARSHAL ROBERTSON
Built at Hull By whom Cochrane & Sons Ltd
Owners Hellyer Bros Ltd Owners' Address
Managers Port belonging to Hull

Used Afloat or in Dry Dock? Name of Dock St Andrew St Destined Voyage Fishing
Cell DBor DBa feet; uE&B feet; f feet
Capacity tons. FPT tons; APT tons; MT feet tons. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Report, No. 35286 Port Hull
The Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.
CHARACTER. For Special Survey. Date of last Survey and of Periodical Surveys. Years Assigned for special survey. Machinery and Boiler Surveys (including date of N.B., if any).
+100 A.I. +L.M.C. 4.23
Stn Hawke 6.24 T.S. 6.24
S.S. Hull No 1. 23

Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs not of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; those being detailed in the body of the report, should be summarised in the form shown below. Whenever the extent of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on this form. State also the dates and initials of any letters respecting this case.
In cases where the Surveyor has not made a special damage report he is required to state whether he has declined his services for this purpose and to whom and why they were declined
Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.
Was a damage report made by anyone else? If so, by whom?

Alterations
Sundries removed from upper decks to Forecastle deck. New steel houses fitted. Fore holdhead in Fish room removed & frame space further fitted & extra beams & bunks fitted in Forecastle New house built over (stbd) fitted out as W.C. & store Boat deck extended aft to this house steel Marconi Wireless house built on top of galley & fitted out for wireless operation.

Nothing has been done this time to the indicated low plates mentioned in the Special Reexam List.

OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Worked								
Worked and Fair'd or Repaired								
Worked or Repaired in place								

CONDITION OF THE	State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	State if Tanks now tested	Engine Room Skylights	(State if on Felt.)
Stenings	Bull-heads	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month
ing	Ceiling	Scuppers	Boats
part in	Cement or Asphalt (State which.)	Cargo Hatchways	Masts, Yards, &c.
mes	Rudder	Hatches	Condition, how ascertained
is	Steering gear and its connections	Planking of Wood Vessels	(State if wedges removed)
part in	Windlass	Caulking	Sails
is	Have Pumps now been examined and found efficient?	Treenails	Equipment letter
part in	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stems	Anchors, No. of
is	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Catches ditto	Cables (State if now ranged)
Plating	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	length (on board) size
		Ditto ditto at other places ditto	Rule length size
		Stringers, Clamps & Shells ditto	Hawser & Warps
		Salting (State if examined.) ditto	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND15, &c."
This vessel as far as now seen is in a good & efficient condition eligible in my opinion to remain as classed without fresh record survey.

Section 20 2 : 2 : 0 Fees applied for, 12/1/1925
Damage or Repair Fee (if any) £ Received by me, 12/3/25
Expenses (if chargeable) £
Surveyor's Fee (if any) £
Committee's Minute
Character Assigned 100% Subject
FRI. 16 JAN 1925
Surveyor to Lloyd's Register of Shipping.
TUES. 19 MAY 1925
Lloyd's Register Foundation
W649-0130