

4 lower man hole flanges of forward and port Boilers built up by O.A. welding and doors refitted.
6 screw stays renewed.

4.90.

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damaged as to spread the ink, or to cause it to show through to the other side.

*Examined
Drawings held by
Supt*

*It is submitted that
this vessel is eligible for
THE RECORD. File 528*

55.28

*RA
1/10/18*

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

