

To Chief Surveyors

Received from Chief Surveyors

SEL'S NAME *Sted S. S. HOGARTH*

Report

*JS*No. *41586***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

re of Survey

When due

Separate endorsement regarding date of build.

Hand pumps to the holds have been dispensed with but it is concluded the Owners are agreeable to fit same or their equivalent if required

❖ *100-A-1. "Shelter Deck with foreboard"*

2 Dks (Steel vpt ws) 2 Shelter Deck (Steel ws)

Cell DB 391' 1479t, MT 31' 1360t, DTA 24' 1015t, FPT 118t, APT 20t.

FK, 7BH to Shelter Dk, Cum, Holes as A.C.P., 8159' F43' on Shelter Dk

Date of build 12.2.1

JS

17.12.24

It is concluded the riveting of the butts of "C" Strake of Shell plating for $\frac{1}{2}$ length amidships and the thickness of "E" Strake at the ends are as approved and not as stated but the Surveyors should be requested to state if this is so.

Is

In