

17 Battery Place,

Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

L'S NAME

H. Lc. "SUDURCO"

Report

myk

No.

32604

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/99.)

of Survey


The 1<sup>st</sup> H. No 2 became due 8. 28 When due

General Examination :- See Secy's letter 1. 8. 30

Solid.

W.L.

10. 3. 31



© 2020

Lloyd's Register  
Foundation

W656-0038

The Secretary,