

No. of Donkey Boilers  
Steam Pressure—  
in Main Boilers

Managers

Owners Address  
(if not already recorded in Appendix to Register)

Port New York

Voyage

sidcat  
Regist

4E

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SEL'S NAME S.S. "SUDURCO"

Rpt. New York

No. 32604.

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

31.  
ACROSS THIS MARGIN  
NOT TO WRITE  
REQUESTED NOT TO WRITE  
THE SURVEYORS ARE REQUESTED NOT TO WRITE

re of Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

*General examination.*


The Special Survey No.2 and the Annual Survey of the water tube boilers became due at the end of 8,28 and 12,27 respectively. The screwshaft survey became due 12,29.

The auxiliary pumps now examined. The propelling machinery also examined but not opened up.

The vessel is laid up.

IT IS SUBMITTED action be deferred.

*29*  
12. 3. 31.



© 2020

Lloyd's Register  
Foundation

W6576-0063

survey.