

Vessel placed in floating dock, bottom cleaned and examined together with stem, keel

Rm. 2.24.

H. C. Hansen

Received by Chief Ship Surveyor

now

Received from Chief Ship Surveyor

VESSEL'S NAME Wood M.S. "MARIENBORG"

Rpt.

Xia.

No. 2717

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor

The class of this vessel is subject to the fore yard being renewed and to a special survey equal to a half time survey being held at 4 and 8 years from the date of build.

The Christiania Surveyors now report the vessel placed on a floating dock and the requirements of a special survey equal to a half time survey complied with and the following repairs effected:- Outside seams part recaulked, salting renewed and minor repairs effected.

The Surveyors state it is the Owners' intention to sail without the fore yard.

It is submitted the vessel appears worthy to remain as classed with record of survey 7,24 Xia. and notation of 5.5.Xia.24, subject to a special survey equal to a half time survey being held at eight years from the date of build and without condition regarding fore yard.

12A1

7,24 Xia.

5.5.Xia.24

subject, etc.

without, etc.



12.8.24.

2020

Lloyd's Register
Foundation

W656-0276

Shipping.